



First Source Inc
1100 Iverleigh Trail
Charlotte, North Carolina 28270
fsimedicalimaging.com

Phone: 800-349-5980
704-845-3049
Fax: 704-845-3069
firstsourceimage@aol.com

First Source Dryview 8100-8900 Training Course Outline

Day 1 8900 DryView Overview

- 1) Overview and Marketplace
- 2) Resource Material
- 3) Operating the 8900
- 4) Theory of operation
 - a. Component ID and Function
 - b. Module Removal / Problem ID / Installation

Day 2 8900 DryView Service Software/PM/Adjustments

- 5) Review and Troubleshooting
- 6) Service Communication Software
- 7) Preventive Maintenance Procedure
- 8) Imager Adjustments

Day 3 8900 DryView System Fundamentals

- 9) Review and Troubleshooting
- 10) MCS overview and component theory
- 11) 8900 Base configuration
- 12) DICOM Discussion and Review
- 13) MIM E series overview
- 14) DICOM Print Server Software Installation and Configuration
- 15) Modality Server Software Installation and Configuration

Day 4 8100 / 8300-8610 Fundamentals

- 16) Review and Troubleshooting
- 17) Overview and Marketplace
- 18) 8100 Operation/PM/Adjustments
- 19) 8300-8610 Operation/PM/Adjustments
- 20) Connectivity overview and Lab

Day 5 DICOM Tools / Course Review

- 21) Review and Troubleshooting
- 22) Special DICOM Tools Installation and Training
- 23) Wrap-up and Review