



First Source Inc
1100 Iverleigh Trail
Charlotte, North Carolina 28270
www.fsmedicalimaging.com

Phone: 800-349-5980
704-845-3049
Fax: 704-845-3069
firstsourceimage@aol.com

First Source Dryview 8100-8700 Training Course Outline

Day 1 8700 DryView Overview

- 1) Overview and Marketplace
- 2) Resource Material
- 3) Operating the 8700
- 4) Theory of operation
- 5) Removal / Installation

Day 2 8700 DryView Adjustments/PM

- 6) Review and Troubleshooting
- 7) System Electronics
- 8) Service Communication Software
- 9) Preventive Maintenance Procedure
- 10) Printer Adjustments
- 11) Direct Connectivity Basics

Day 3 DICOM Basics/9410/MIM Overview

- 12) DICOM Introduction
- 13) DICOM/9410 PacsLink/MIM Products
- 14) Print Server Installation and Configuration
- 15) Modality Server Installation and Configuration

Day 4 8100 / 8300-8610 Fundamentals

- 16) Overview and Marketplace
- 17) 8100 Operation/PM/Adjustments
- 18) 8300-8610 Operation/PM/Adjustments
- 19) Connectivity overview and Lab

Day 5 Course Review

- 20) Troubleshooting and Technical Support
- 21) Wrap-up and Review